

# Oil Field Environmental Incident Summary

**Incident:** 20151215165559      **Date/Time of Notice:** 12/15/2015 16:55

**Responsible Party:** Hess Bakkan Investments LLC.

**Well Operator:**

**Well Name:**

**Field Name:**

**Well File #:**

**Date Incident:** 12/9/2015

**Time Incident:** 10:00

**Facility ID Number:**

**County:** MCKENZIE

**Twp:** 152

**Rng:** 95

**Sec:** 7

**Qtr:**

**Location Description:** the coordinates are 47.998056, -102.884444. Tesoro was installing a pipeline rightaway and encountered impacted soils.

**Submitted By:** Alberto Yates

**Received By:**

**Contact Person:** Troy Brunsell  
3015 16th St. SW Suite 20  
Minot, ND 58701

**General Land Use:** Other - Described Above

**Affected Medium:** Topsoil

**Distance Nearest Occupied Building:** 1800 Feet

**Distance Nearest Water Well:** 1800 Feet

**Type of Incident:** Other

**Release Contained in Dike:** Yes - On Pipeline ROW

**Reported to NRC:** No

**Spilled Units**

**Recovered Units**

**Followup Units**

**Oil**

**Brine**

**Other**

**Description of Other Released Contaminant:**

Impacted soils

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

No immediate risk to report at this time

**Areal Extent:**

Area extent unknown how ever 3 truck loads of dirt has been stock piled for disposal

**Potential Environmental Impacts:**

Environmental impacts to soils around Tesoro pipeline right-away

**Action Taken or Planned:**

Tesoro stopped work when impacted soil was discovered. Tesoro contacted Hess Environmental. Verbal notification was made to Cody Vanderbusch by Alex Beach on 12/9/2015 at 1053 am. Hess will be following up with investigations 12/16/2015 on site.

**Wastes Disposal Location:** .All recovered waste will be disposed at an approved waste disposal facility.

**Agencies Involved:****Updates**

---

**Date:** 12/16/2015 **Status:** Reviewed - Follow-up Required

**Author:** Crowdus, Kory

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Spoke to contact person. Impacted soils were uncovered while working in the area. They are in the process of trying to determine the source. They will notify NDDoH of their findings. More followup required.

---

**Date:** 12/30/2015 **Status:** Inspection

**Author:** O'Gorman, Brian

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Arrived near the location at 11:40. GPS coordinates showed that the incident was approximately .3 mile east of the eastern section line. Due to snow-covered conditions and walking distance, the inspection was put on hold. Additional information from the reporting company needed before the next inspection. More followup needed.